

Product Safety Recall

Tikka .308 Calibre Ammunition for a Centrefire Rifle (All 20 and 50 cartridge packets and 200 cartridge in plastic containers)



Sold at Beretta Australia Firearms Dealers February 2016 - October 2019

What are the defects? Corrosion can occur on the inside of new or reloaded ammunition cartridges, which weakens their strength.

What are the hazards? The weakened cartridge may split on firing rifle, causing burning gases to leak from the rifle and rifle to malfunction during use. This may pose a risk of serious injury or death to the user. This hazard may also occur in reloaded cartridges.

What should consumers do? Consumers should immediately stop using the cartridges (new or reloaded) and contact their nearest Beretta Australia Firearms Dealer for replacement cartridges or a full refund of the purchase price.

For other options for replacement or refund please visit
<https://www.berettaaustralia.com.au/Tikka308recall>

Contact Details: For further information, contact the nearest Beretta Australia Firearms Dealer directly or contact Beretta Australia on 03 9799 5100 between 8:30am and 5:30pm AEDT, by e-mail at info@berettaaustralia.com or visit <https://www.berettaaustralia.com.au>

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information